

# The Palms: Before ~ After Photos

351 East Palm Drive, Anytown, USA 01995


PH 987-654-3210 \* FAX 987-654-3211



# The Palms: Before ~ After Photos

351 East Palm Drive, Anytown, USA 01995

PH 987-654-3210 \* FAX 987-654-3211




First Floor EXIT

## The Palms: Before ~ After Photos

---

351 East Palm Drive, Anytown, USA 01995

PH 987-654-3210 \* FAX 987-654-3211



← 2 —

Second Floor *EAST*

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

4 of 22



01-2007-05-02\_002 P\_E: Before - Facility identification sign. Note broken sign lighting.



02-2009-04-23\_DSC09363: After - New monument sign (name edited for privacy)



03-2007-05-02\_006 P\_E: Before - Main entrance to Palm East.



04-2009-04-23\_DSC09261: After - repaired and re-painted wood.

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

5 of 22



05-2009-04-23\_DSC09433: After - repaired and re-painted wood.



06-2007-05-02\_013 P\_E: Before - West elevation of Palm East (looking north).



07-2007-05-02\_014 P\_E: Before - Palm East service entrance - water heater room & kitchen delivery area.



08-2009-04-23\_DSC09438: After - repaired and re-painted wood.

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

6 of 22



09-2007-05-02\_033 P\_E: Before - Palm East - west elevation. note rotten wood trim on 2nd floor balconies.



10-2007-05-02\_034 P\_E: Before - Detail - rotten wood trim on 2nd floor balconies.



11-2009-04-23\_DSC09437: After - repaired and re-painted wood.



12-2007-05-02\_042 P\_E: Before - Detail - rotten trim on 2nd floor balcony.

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

7 of 22



13-2007-05-02\_158 P\_E: Before - Interior courtyard.



14-2009-04-23\_DSC09246: After - repaired and re-painted wood.



15-2009-04-23\_DSC09359: After - repaired and re-painted wood.



16-2009-04-23\_DSC09436: Before - Front entrance doors need to be re-finished.

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

8 of 22



17-2009-07-31\_DSC09399: After - Re-finished front entry doors.



18-2009-07-31\_DSC09398: After - Re-finished front entry doors.



19-2007-05-02\_054 P\_E: Before - Front entry with reception desk and door into courtyard.



20-2007-05-02\_053 P\_E: Before - Front entry.

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

9 of 22



21-2007-05-02\_055 P\_E: Before - Reception desk at Palm East entrance.



22-2007-05-02\_093 P\_E: Before - Palm East - typical 2nd floor corridor. Wood base, painted walls, no handrails, wallpaper border transition. Paint and border are



23-2008-05-19\_DSC08586: Before - Palm East - typical 2nd floor corridor. Wood base, painted walls, no handrails, wallpaper border transition. Paint and



24-2007-05-02\_119 P\_E: Before - 2nd floor West Hall looking south.

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

10 of 22



25-2007-05-02\_124 P\_E: Before - 2nd floor east hall @ north end. Note missing wallpaper border - staff is in the process of installing border after painting



26-2007-05-02\_087 P\_E: Before - Detail - wallpaper border peeling at wall corner. (Note - staff has not yet begun 1st floor painting improvements.



27-2009-07-31\_DSC09270: After - Main entrance & corridors



28-2009-07-31\_DSC09271: After - Main entrance & corridors

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

11 of 22



29-2009-07-31\_DSC09274: After - Main entrance & corridors



30-2009-04-23\_DSC09302: After - Main entrance & corridors



31-2009-07-31\_DSC09278: After - Main entrance & corridors



32-2009-07-31\_DSC09325: After - Main entrance & corridors

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

12 of 22



33-2009-07-31\_DSC09327: After - Main entrance & corridors



34-2009-07-31\_DSC09323: After - Main entrance & corridors



35-2009-07-31\_DSC09376: After - Main entrance & corridors



36-2009-07-31\_DSC09384: After - Main entrance & corridors

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

13 of 22



37-2007-05-02\_066 P\_E: Before - Main dining room.



38-2007-05-02\_068 P\_E: Before - Main dining room - screen wall with kitchen access.



39-2007-05-02\_067 P\_E: Before - Main dining room.



40-2009-07-31\_DSC09306: After - Main dining room

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

14 of 22



41-2009-07-31\_DSC09295: After - Main dining room



42-2009-07-31\_DSC09298: After - Main dining room



43-2007-05-02\_061 P\_E: Before - Living room.



44-2007-05-02\_062 P\_E: Before - Living room.

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

15 of 22



45-2007-05-02\_059 P\_E: Before - Living room.



46-2007-05-02\_063 P\_E: Before - Living room.



47-2007-05-02\_064 P\_E: Before - Living room.



48-2007-05-02\_057 P\_E: Before - Living room.

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

16 of 22



49-2007-05-02\_058 P\_E: Before - Living room.



50-2007-05-02\_065 P\_E: Before - Living room.



51-2009-07-31\_DSC09250: After - 1st floor living room.



52-2009-07-31\_DSC09256: After - 1st floor living room.

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

17 of 22



53-2009-07-31\_DSC09253: Before - 1st floor living room.



54-2009-07-31\_DSC09237: After - 1st floor living room.



55-2009-07-31\_DSC09242: Before - 1st floor living room.



56-2009-07-31\_DSC09223: After - 1st floor living room.

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

18 of 22



57-2009-07-31\_DSC09241: Before - 1st floor living room.



58-2009-07-31\_DSC09224: After - 1st floor living room.



59-2009-07-31\_DSC09229: Before - 1st floor living room.



60-2009-07-31\_DSC09227: After - 1st floor living room.

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

19 of 22



61-2009-07-31\_DSC09267: After - 1st floor living room.



62-2007-05-02\_102 P\_E: Before - 2nd floor TV-Activity room.



63-2007-05-02\_103 P\_E: Before - 2nd floor TV-Activity room.



64-2007-05-02\_105 P\_E: Before - 2nd floor TV-Activity room.

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

20 of 22



65-2009-07-31\_DSC09490: Before - 2nd floor Library & Movie Room



66-2009-07-31\_DSC09509: After - 2nd floor Library & Movie Room



67-2009-07-31\_DSC09494: After - 2nd floor Library & Movie Room



68-2009-07-31\_DSC09497: After - 2nd floor Library & Movie Room

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

21 of 22



69-2007-05-02\_109 P\_E: Before - 2nd floor game-recreation room.



70-2007-05-02\_110 P\_E: Before - 2nd floor game-recreation room.



71-2009-07-31\_DSC09343: After - 2nd floor game-recreation room.



72-2009-07-31\_DSC09350: After - 2nd floor game-recreation room.

## The Palms: Before ==> After Photos

Anytown, USA; July 31, 2009

22 of 22



73-2009-07-31\_DSC09345: Before - 2nd floor game-recreation room.



74-2009-07-31\_DSC09349: After - 2nd floor game-recreation room.